

**PROFORMA REGARDING SAFE DRINKING WATER AND SANITARY
CONDITION CERTIFICATE.**


No. 263

Date : 13/03/23

It is certified that an inspection team headed by ...JITENDRA LAKRA
ASSISTANT ENGINEER, DRINKING WATER AND SANITATION
SUB-DIVISION, GUMLA (Name of Officers with designation) from ...D.W & S
SUB-DIVISION, GUMLA ... (Name of Department / Office) inspected the

School Name - KGBV GUMLA (20160819505), Village - WARD 14, Block -
GUMLA, District - GUMLA, Pin - 835207, Jharkhand on 13/03/2023 ... (Date)
and found that the KGBV GUMLA has safe drinking water facilities for the students
and members of staff of the institution and is maintaining the hygienic sanitation
condition in the school building & the campus as per the norms prescribed by the
Central/State/U.T Govt.

The above valid for a period of

Signature with Seal :  13/03/2023

Name : JITENDRA LAKRA

Designation : ASSISTANT ENGINEER

To
Principal,
KGBV GUMLA,
WARD 14, GUMLA, GUMLA,
Pin - 835207, Jharkhand.

K. S. Singh
13/03/23
कार्डिन-सह-सिक्तिक
कस्तुरबा गौरी बालिका विद्यालय
गुमला (झारखण्ड)

Assistant Engineer
D W & S Sub Division Gumla-II